



# IP-STAT-04

Flowlink 4 for Windows



IP-STAT-05  
Flowlink 4 for Windows




Velocity  
meter  
malfunction.

0750  
9/23/02  
Sampler Enabled


0731  
9/25/02  
Sampler  
Disabled

# IP-STAT-06

Flowlink 4 for Windows




IP-STAT-07  
Flowlink 4 for Windows



# IP-STAT-08


Flowlink 4 for Windows



0857  
9/23/02  
Sampler  
enabled

0845  
9/25/02  
Sampler  
disabled.


IP-STAT-09  
Flowlink 4 for Windows






# IP-STAT-10

Flowlink 4 for Windows



# IP-STAT-01

Flowlink 4 for Windows



10116102  
C 1118  
sampler  
initiated


10118102  
C 0548  
sampler  
disabled



Note: Problems w/ Transducer.  
 Last Velocity Readings  
 10/10/02 = - 0.65  
 based on levels  
 Avg Flow =  
 - 8.10 cfs

# IP-STAT-02

Flowlink 4 for Windows




Sampler  
 enabled  
 on 10/16/02 @ 1200

Sampler  
 disabled  
 on 10/17/02 @ 2158

# IP-STAT-03

Flowlink 4 for Windows




10/16/02  
0 1209  
Sampler enabled.

10/17/02  
0 2151  
Sampler disabled.

# IP-STAT-04

Flowlink 4 for Windows




10/16/02  
C 1121  
sampler  
enabled.

10/17/02  
C 0130  
peak.

10/18/02  
C 0845  
sampler  
disabled.


# IP-STAT-05

Flowlink 4 for Windows



# IP-STAT-06


Flowlink 4 for Windows





# IP-STAT-07


Flowlink 4 for Windows





# IP-STAT-08

Flowlink 4 for Windows




10/16/02  
C 1400  
Sampler  
enabled.

10/17/02  
C 2349  
Power Failed  
Sampler  
disabled.

# IP-STAT-10

Flowlink 4 for Windows



Oct 2002

10/16/2002 12:00:00 AM - 10/17/2002 3:00:00 PM

10/16/02  
@ 1210  
sampler  
initiated.

10/17/02  
@ 1423  
sampler  
disabled.